

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definiti	Err rs
1	BRS	739	347/19.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 13:59			0
2	BRS	132	347/19.ccls. and (drop dot droplet) with (velocity speed)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:39			0
3	BRS	5	(347/19.ccls. and (drop dot droplet) with (velocity speed)) and thickness with (medium media paper)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:12			0
4	BRS	913	(347/8 347/19).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:12			0
5	BRS	42	(347/14 347/16).ccls. and thickness with (medium media paper)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:37			0
6	BRS	1509	(347/8 347/19 347/14 347/16).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:38			0
7	BRS	515	((347/8 347/19 347/14 347/16).ccls.) and (drop dot droplet) with (velocity speed detect\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:40			0
8	BRS	3	((((347/8 347/19 347/14 347/16).ccls.) and (drop dot droplet) with (velocity speed detect\$3)) and air adj gap	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:41			0
9	BRS	3	347/8.ccls. and 347/19.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 12:47			0
10	BRS	7	347/8.ccls. and (347/14 347/16).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 14:11			0
11	BRS	4	5576744.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 13:25			0
12	BRS	18	("4328504"   "4435674"   "4847638"   "4907013"   "4977459"   "5157411").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 13:27			0
13	BRS	36	4977459.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 13:36			0
14	BRS	1519	(fault faulty malfunction\$3) with (nozzle orifice)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 14:13			0
15	BRS	250	((fault faulty malfunction\$3) with (nozzle orifice)) and (inkjet (ink liquid) with (jet eject))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 14:15			0
16	BRS	237	((((fault faulty malfunction\$3) with (nozzle orifice)) and (inkjet (ink liquid) with (jet eject))) ) not 347/19.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 14:17			0
17	BRS	3	4489335.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/15 14:17			0
18	BRS	742	347/19.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 14:00			0
19	BRS	17	347/19.ccls. and (drop droplet) with (velocity speed) with (compar\$4 difference)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 14:27			0
20	BRS	16	347/19.ccls. and (drop droplet) with (velocity speed) with (relative)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 14:36			0
21	BRS	44534	347/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 14:37			0
22	BRS	64	347/\$.ccls. and (printhead print adj head) with tilt	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 15:41			0
23	BRS	18	("4784503"   "4787759"   "4906115"   "4979835"   "5000590"   "5083143").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 14:42			0
24	BRS	2	5388919.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 14:45			0
25	BRS	3	4626867.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 15:42			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definiti	Errors
26	BRS	11	4626867.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/10/16 15:42			0